

<b>Subject:</b>  SEAT BELT RETAINER BREAKS	<b>Bulletin No:</b> 08-001/08
	<b>Last Issued:</b> 1/4/2008

## APPLICABLE MODEL(S)/VINS


2007 CX-9 with VINs before JM3 TB\*\*\*\* \*\* 117348 (produced before April 1, 2007)

2006-2007 Mazda5 with VINs before JM1 CR\*\*\*\* \*\* 153483 (produced before March 1, 2007)

## DESCRIPTION

Some customer may complain that seat belt retainer clips for 2nd (Mazda5) or 3rd (CX-9, Mazda5) row seat are easily broken off. As a mass-production change, the construction of the seat belt retainer clip has been revised.

Customers having this concern should have their vehicle repaired using the following repair procedure.



## REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the broken seat belt clip with a modified one.

### NOTE:

- The seat belt clip can only be installed in one direction.

3. Verify repair.

<b>Bulletin No:</b> 08-001/08 © 2008 Mazda Motor of America, Inc.	<b>Last Issued:</b> 1/4/2008
--	------------------------------

## PART(S) INFORMATION

Part Number	Description	Qty.	Notes
C235-68-AD2A 02	Clip	1	---

## WARRANTY INFORMATION

### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair. Refer to the Warranty Wizard for warranty term information.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	92
Damage Code	9E
Part Number Main Cause	C235-68-AD2A 02
Quantity	1
Operation Number / Labor Hours:	XXC1LXRX / 0.2 Hrs