

VIN  or Model Year 2010  Model CX9  window switch

General Information ☐ Engine ☐ Suspension ☐ Transmission/Transaxle ☐ HVAC ☐

Steering ☐ Brakes ☐ DriveLine/Axle ☐ Restraints ☐

## MASTER WINDOW SWITCH LEDS NOT ILLUMINATED

### Applicable Models

Model	Starting S/N	Ending S/N	Model Spec
CX9 2010-2010	000000	ZZZZZZ	FROM PROD DATE 04/08/10

### Related Category/Subcategory/Symptoms

Body and Accessories / Electrical Systems / Improper Operation

Body and Accessories / Power Systems / Improper Operation

Body and Accessories / Lighting Systems / Improper Operation

### MTOL - 7368 Dealer Repair Information

#### Symptom and Conditions

The LEDs for the right front, left rear, and right rear window switches located on the driver side master switch do not illuminate.

#### Repair Procedure

There was a change made starting 04/08/2010 that eliminated these LEDs. Do not attempt repairs as this condition is normal and is not covered under warranty.

\*\*\* MTips newsletter July/August 2010 \*\*\*