

Mazda Canada Inc.

55 Vogell Road
Richmond Hill, ON L4B 3K5
Tel.: (905) 787-7000
Fax: (905) 787-7135
www.mazda.ca



VIN#

November 08, 2007

**RE: 2007 CX-7, 2007 MAZDASPEED3, 2006-2007 MAZDASPEED6, and 2006 Mazda6 2.3L
OBD-II Compliance Voluntary Emission Recall Campaign 4907H**

Dear Mazda Owner:

Mazda Motor Corporation has decided to conduct an Emission Recall Campaign to reprogram the Powertrain Control Module (PCM) on certain Mazda vehicles per the schedule below.

| Model | Build Date Range |
|-----------------------------|--|
| 2007 CX-7 | February 14, 2006 through April 28, 2007 |
| 2007 Mazdaspeed3 | June 28, 2006 through May 31, 2007 |
| 2006-2007 Mazdaspeed6 | August 4, 2005 through June 30, 2007 |
| 2006 Mazda6 2.3L 4-cylinder | June 2, 2005 through June 27, 2006 |

Your vehicle may be equipped with an improperly functioning on-board emission-related diagnostic system that violates emission standards and regulations.

If you are a recipient of this notice, your vehicle is included in this recall.

What is the problem?

The monitor function used to detect Short Fuel Trim maximum threshold strategy is inoperative. Due to the lack of this monitor function, the OBD system is not capable of detecting the malfunction that causes the adaptive feedback control to be exceeded.

In addition, it is possible that the malfunction may not be detected by any other OBD monitor function, therefore the MIL may not illuminate. Consequently, the vehicle operator would not be advised about the malfunction.