

For all adjustments, mounting will be provided FREE. You will be responsible for the cost of balancing and a new valve stem, if necessary, as well as the of service, the servicing dealer will either repair it or, at the dealer's option, make an allowance toward the purchase of a new tire. In the event that you are unable to provide the information listed above, this warranty shall be void. • The original invoice for the purchase of the covered tire. In order to receive warranty service on your tire, you must provide the servicing dealer with the following: This limited tire warranty is issued and serviced by the American Car Care Centers Dealer from whom you purchased it, and is separate from any other warranty. In addition to, the warranty provided by the manufacturer of your tire. The warranty coverage applies only to the original purchaser. unserviceable.

Telephone

Vehicle (VIN)

License

Year:

06

Technician

Mileage

Time Printed

3/28/07 9:38 AM

Mazda : Mazda6 : Sedan/Hatchback : 2.3L Turbo All Wheel Drive (Mazdaspeed) : 2006

Front : Left

Actual	Before	Specified Range
-0.7°	-0.7°	-1.3° 0.7°
4.3°	4.3°	2.9° 4.9°
0.01°	-0.19°	-0.09° 0.28°
5.0°	5.0°	
4.3°	4.3°	

Camber

Caster

Toe

SAI

Included Angle

Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0.6°	-0.6°	-1.3° 0.7°
4.1°	4.1°	2.9° 4.9°
0.01°	-0.14°	-0.09° 0.28°
5.1°	5.0°	
4.5°	4.5°	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0.1°	-0.1°	-1.5° 1.5°
0.1°	0.1°	-1.5° 1.5°
-0.1°	0.0°	
0.02°	-0.33°	-0.18° 0.55°

Rear : Left

Actual	Before	Specified Range
-1.9°	-2.1°	-2.6° -0.6°
-0.03°	0.17°	-0.09° 0.28°

Camber

Toe

Rear : Right

Actual	Before	Specified Range
-2.0°	-2.2°	-2.6° -0.6°
-0.02°	0.20°	-0.09° 0.28°

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0.1°	0.1°	-1.5° 1.5°
-0.06°	0.37°	-0.18° 0.55°
0.00°	-0.01°	-0.80° 0.80°