



LABOR & PARTS
 # 1 22MAZZDENL DIAG ENG NOISE/LEAK TECH(S):5090 WARRANTY
 CUSTOMER STATES:CUST STATES THAT WHEN CAR SITS AT IDLE F
 OR A PERIOD OF TIME THERE IS BLUE SMOKE COMING OUT OF TH
 E EXHAUST AND IT SMELLS ALOT LIKE BURNT OIL
 TEST DROVE VEHICLE AND INSPECTED AND FOUND BLUE SMOKE FROM
 EXHAUST AFTER VEHICLE WARMED UP.REMOVED INTERCOOLER AND
 FOUND OIL INSIDE FROM TURBO LEAKING.CALLED TECH LINE
 REF. #563575 AND CHECKED COMPRESSION 185.AND LEAKDOWN
 WAS LESS THAN 10%.CHECKED PCV VALVE AND FOUND OK.
 REPLACED TURBO CHARGER AND TEST DROVE.ALL OK AND WORKING
 NORMAL NOW.

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

SERVICE HOURS
 Monday-Friday 7:00-6:00

PARTS HOURS
 Monday-Friday 7:30-5:30

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
JOB # 1	1	L33E-13-146A	STUD			WARRANTY
JOB # 1	8	L3K9-13-146A	STUD,SURGE			WARRANTY
JOB # 1	1	L3K9-13-710	GASKET,TUR			WARRANTY
JOB # 1	1	L3K9-14-264	GASKET,OIL			WARRANTY
JOB # 1	1	L3K9-14-293	GASKET,OIL			WARRANTY
JOB # 1	4	9956-21-200	GASKET			WARRANTY
JOB # 1	4	9956-21-400	GASKET			WARRANTY
JOB # 1	1	L3Y1-13-70ZB	TURBO CHAR			WARRANTY
JOB # 1	1	L3K9-13-460	GASKET,EX.			WARRANTY
JOB # 1	1	L3F2-13-490	GASKET			WARRANTY
JOB # 1	1	L3A1-40-581	SEAL RING			WARRANTY
JOB # 1	15	JE10-40-355	NUT			WARRANTY
JOB # 1	10	9XG0-44-747L	STUD			WARRANTY
JOB # 1 TOTAL PARTS					0.00	
JOB # 1 TOTAL LABOR & PARTS					0.00	

IMPORTANT
 You may receive a questionnaire from J.D. Powers. If, for any reason you feel you cannot rate our services completely satisfied, please contact Service & Parts Director Paul Schwegman at 763-566-5600.
 A "Completely Satisfied" rating does not mean we are perfect but rather that we did our job well and served you professionally.

2 00MAZZ99PMI FULL CIRCLE TECH(S):5090 WARRANTY
 PERFORM MAZDA FULL CIRCLE SERVICE INSPECTION.
 COMPLETED MAZDA FULL CIRCLE SERVICE INSPECTION. SEE ATTACHED REPORT CARD.

3 45MAZZRENTAL RENTAL VEHICLE TECH(S):5090 WARRANTY
 RENTAL VEHICLE
 2241
 RENTAL VEHICLE

4+03MAZZTIREG TIRE STATUS GREEN TECH(S):5090 WARRANTY
 CHECK TIRES/MEASURE TIRE TREAD DEPTH
 50% OR MORE REMAINING



ALL PARTS NEW ORIGINAL EQUIPMENT UNLESS OTHERWISE SPECIFIED.

THANK-YOU