



965 WORCESTER ROAD (ROUTE 9 WEST) • WELLESLEY, MA 02482 • 781-235-6000

CUSTOMER No.	ADVISOR	TAG No.	INVOICE DATE	INVOICE No.
	LABOR RATE 99.00	LICENSE No.	MILEAGE	COLOR
	YEAR / MAKE / MODEL 06/MAZDA/SPEED6/4 DOOR SEDAN		DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. No.		SELLING DEALER NO.	PRODUCTION DATE
	F. T. E. No.	P.O. No.	R.O. DATE	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO:	

LABOR & PARTS-----
J# 1 06F0Z CLUTCH TECH(S):348 WARRANTY
REPLACE CLUTCH ASSEMBLY WITH UPDATED PARTS DUE TO CLUTCH
PEDAL DIFFICULT TO OPERATE
REFERENCE TSB 05-009/08, GROUP "A" VEHICLE, REP INSPECTED
CLUTCH PEDAL ENGAGES HIGHER CAUSING STALLING, DIFFICULTY
SHIFTING, INCREASED AND UNNECESSARY CLUTCH WEAR
REPLACED CLUTCH PEDAL, CLUTCH COVER AND CLUTCH DISC
ASSEMBLIES AS PER TSB 05-009/08, PERFORMED ALIGNMENT AND
ROADTESTED

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE
JOB # 1	1		GP4L-41-300A	PEDAL, CLUTCH	
JOB # 1	1		L304-16-410B	CLUTCH CVR	
JOB # 1	1		L304-16-460B	CLUTCH DISC	
JOB # 1	1		P017-27-421A	CLIP	
JOB # 1	1		T060-26-169A	PIN, SNAP	
JOB # 1	1		GJ6A-33-023C	BUSH	
JOB # 1	1		GJ6A-33-024C	BUSH	
JOB # 1	1		A601-17-117	GASKET	
JOB # 1	1		L3A1-40-581	SEAL RING	
JOB # 1	1		LN01-27-3A2	RING, O	
JOB # 1	1		LN01-27-3A3	SEAL, OIL	
JOB # 1 TOTAL PARTS					0.00
JOB # 1 TOTAL LABOR & PARTS					0.00

J# 2+60F0Z LOANER CAR TECH(S):348 WARRANTY
COURTESY TRANSPORTATION VEHICLE
(\$10.00 GAS FEE)

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE
JOB # 2 TOTAL PARTS					0.00
JOB # 2 TOTAL LABOR & PARTS					0.00

J# 3+99F0Z99P QUALITY CARE TECH(S):348 WARRANTY
PLEASE PERFORM QUALITY CARE REPORT CARD
COMPLETED QUALITY CARE REPORT CARD

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE
JOB # 3 TOTAL PARTS					0.00
JOB # 3 TOTAL LABOR & PARTS					0.00

J# 4+99F0ZZBATTG GREEN BATTERY TECH(S):348 WARRANTY
BATTERY CHECKED, OK AT THIS TIME.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE
JOB # 4 TOTAL PARTS					0.00
JOB # 4 TOTAL LABOR & PARTS					0.00

J# 5+99F0ZZBRKN BRAKE STATUS NOT TECH(S):348 WARRANTY
BRAKE MEASUREMENTS NOT TAKEN THIS SERVICE VISIT